

2018 BOND IMPROVEMENTS*



Bear Creek Articulation Area

	Build new facility on same property	Expand with addition	Remodel building interior	Additions/renovations for programs	Growth accommodations	Remove modular buildings	Security camera & lock updates	Secure entries & office locations	New, more secure exterior doors	More secure & energy-efficient windows	Update existing technology	Landscaping & field improvements	Update interior paint, wall-coverings	Update electrical wiring & increase capacity	Update HVAC, plumbing & piping	Repair & update caulk, trim & window sills	New paint to protect exterior	Commercial kitchen improvements	Parking lot & sidewalk improvements	Replace old playground equipment	Replace old furniture	Replace old carpet & floor tile	Replace movable partitions	Replace old sinks, cabinets & shelving	Replace interior lighting with LEDs	Replace worn roofing
Bear Creek High							•	•		•			•	•										•		
Bear Creek K-8							•	•		•			•	•										•		•
Carmody Middle					•	•	•			•		•	•	•				•			•		•	•	•	
Green Gables Elementary		•			•	•	•	•	•		•	•	•					•	•	•	•	•	•	•	•	
Kendallvue Elementary					•	•	•	•		•			•	•				•		•		•	•	•		
Kendrick Lakes Elementary	•																									
Peiffer Elementary						•	•	•					•	•				•	•	•			•			
Red Rocks Elementary							•	•	•	•			•	•				•	•	•	•	•		•	•	
Westgate Elementary						•	•	•	•				•	•				•			•	•	•	•	•	

*Based on 2018 Capital Improvement Plan. Subject to project scope.

Red Rocks Elementary School Improvements

- Replace old playground equipment.
- Update security cameras & classroom security door hardware.
- Secure building vestibules, entries & office location.
- New, more secure & energy-efficient windows.
- Update old electrical wiring, panels & increase capacity.
- Update old heating & cooling equipment, plumbing fixtures & piping.
- Commercial kitchen improvements.
- Replace:
 - Old student furniture, cafeteria tables & library furniture;
 - Interior lighting with energy-efficient LEDs; &
 - Old ceilings.



Age of Facility: 63 years (built in 1955)
Square Footage: 29,177

Enrollment: 295

**BUILDING
CONDITION:
POOR**

FCI: 35.8%

FCI is a measurement of the physical condition of the school's interior, exterior & grounds.

Good: less than 10%
Fair: 11% to 30%
Poor: greater than 30%.

Estimated cost of proposed improvements: \$2,071,031. Subject to change per final project scope.